## SERVICE BULLETIN



No. : 0IVL20040003 Date : 2004-06-15

Model			Factory	Facto	ry Model	Suffix	Model I	No.	Factory	Factory Mod	el Suffix	Model	No.	
		EKHQ	MW-3	BOLZ10	AALZKZ	Z L30W2	6	EKHQ	MW-30LZ10	ACLLK	C MW-30	LZ10		
			EKHQ	MW-3	30LZ10	AWPLK:	Z MW-30	LZ10						
	Buyer Name Buyer C		Buyer Cod	de Bu	yer Name	Buyer	Code	Buyer Name	Buyer Co	de				
Buyer		LGEUS	l	JS000001	I LG	EAI	US000	0002	ZENITH	US00751	5			
EFFECTIVE DATE			2004-06-15				EFFECTIVE FROM(SERIAL NO.)					june 2004		
Subject To repair image spread														
No.	Loc No.		Before Change				After Change				Note	K-Code	Remark	
140.		Pa	rt No	D	ESC./SP	EC.	Part	No	DES	SC./SPEC.	14010	it code	Roman	

## Reason Of Change

To repair an image spread problem, please perform the following:

- 1) On the main board, check solder conidtion of R752~R761 (P/N:0RH0222D622) & P005B (6602T11001A). Perform re-soldering if necessary.
- 2) Check P005B and Link cable (P/N:6631V00006Q) connection.
- 3) Change Link cable (P/N:6631V00006Q).
- 4) Check Link cable (P/N:6631V00006Q) and LCD Module connection.
- 5) Check solder conidtion of wafer (Circuit No.:CN5)'s and perform re-soldering on T-con Board on the LCD Module.

## \*\* FILE THIS SERVICE BULLETIN WITH YOUR SERVICE MANUAL

	NOTE(**) : IN	KEY-WORD CODE	
	Parts Set		
А	Original Early	Original or new parts may be used in early or late production sets.	1. To improve performance
	New Late	Use original parts until exhausted, then stock new parts.	2. To improve productivity
В	OriginalEarly	Original parts may be used in early production sets only.  New parts may be used in early or late production sets.	3. To improve reliability
	New Late	Use original parts where possible, then stock new parts.	4. Change of material or dimension
С	Original Early	New parts only may be used in early or late production sets.	5. Addition
	New Late	Stock new parts.	6. Deletion
D	OriginalEarly	Original parts only may be used in early production sets.  New parts may be used in late production sets only.	7. Correction
	New Late	Stock original and new parts.	

CHIEF ENGINEER , approved Factory.